


















Packing list

Nordpeis

IN-0N21U-010, N-21U Insert

 1x 22-0N21U-310	 1x IS-0N21U-080 (22-00N20-180)	 1x IS-0N21U-080 (IP-0N20U-010)	 2x IP-0N20A-010
 1x IS-0N21U-080 (22-0N21U-370)	 1x IS-0N21U-080 (22-40313-200)	T20  1x IS-0N21U-080 (21-70000-T20)	fi8x24  4x IS-0N21U-080 (21-50000-022)
M8x20  4x IS-0N21U-080 (21-30006-020)	M4x8  8x IS-0N21U-080 (21-30011-408)	M4x5  2x IS-0N21U-080 (21-30001-405)	No 3  1x IS-0N21U-080 (21-70000-030)
No 2.5  1x IS-0N21U-080 (21-70000-025)	User manual  1x IS-0N21U-080 (24-0N21U-M10)	 1x IP-0N20U-040	 1x IS-0N21U-080 (22-00N20-290)
 1x IS-0N21U-080 (22-0N29U-950)	 2x IC-0N20A-270	 1x IS-0N21U-080 (22-0N21U-070)	 1x IS-0N21U-080 (24-00028-000)

