

AF-MON00-360 Monaco low + bench - fast. parts

21-30011-408 Screw Spiralform Plus WN1352 SF M4 x 8 12x

21-30001-666 Screw with wascher M6x16 ISO 7380 ZN 24x

21-50001-018 Washer fi6x18 Din 9021 12x

21-00000-006 Nut M6 Din 934 12x

21-40001-045 Screw M6x45 DIN 916 6x

22-MON00-110 Corner top (standard) 2x

22-MON00-390 Corner bottom (low) 2x

